HONDA Service Bulletin

Model	Applicable To	File Under	Bulletin No.
ALL	**1995.5 PASSPORT and ALL 1996 and Later Models**	**SPECIAL TOOLS**	**96-037**
			Issue Date **AUG 5, 1996**

SRS Inflator Simulator Tools

Use the special tools in the right column of the cross reference chart for SRS troubleshooting in the Service Manuals.

These special tools shown in the Service Manual have been replaced (correct your '96 manuals).	These special tools replace those shown on the left. Be sure to connect the SRS Simulator Lead to the proper port on the SRS Inflator Simulator as shown below. NOTE: These tools may be shown in some current Service Manuals.
SRS Service Connector **T/N 07SAZ-SW50200** 	**Replaced by:** **SRS Simulator Lead C** **T/N 07TAZ-SZ5011A** **SRS Inflator Simulator** **T/N 07SAZ-TB4011A** 
SRS Service Connector, 2Ω **T/N 07TAZ-SZ50200** 	**Replaced by:** **SRS Simulator Lead C** **T/N 07TAZ-SZ5011A** **SRS Inflator Simulator** **T/N 07SAZ-TB4011A** 
PASSPORT ONLY **SRS Driver/Passenger Load Tool** **T/N J-41433** 	**Replaced by:** **SRS Simulator Lead A** **T/N 07SAZ-TB4012A** **(two required)** ***Driver/Passenger Airbag Assembly*** **SRS Inflator Simulator** **T/N 07SAZ-TB4011A** **NOTE: "JUMPER" port is not used on the Passport.** **SRS Simulator Lead B** **T/N 07SAZ-TB4013A** ***Steering Column*** 

©1996 American Honda Motor Co., Inc. – All Rights Reserved

CUSTOMER INFORMATION: The information in this bulletin is intended for use *only* by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your car. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your car, or that your car has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.